

Thread Cleaning Tap



1/4? - 20 HSS 4 Flute bottoming hand tap

- Use to clean dirt and debris from threads where table glide was missing
- Prevents cross-threading and guarantees proper installation

